



UNITED STATES PATENT AND TRADEMARK OFFICE

UNITED STATES DEPARTMENT OF COMMERCE
United States Patent and Trademark Office
Address: COMMISSIONER FOR PATENTS
P.O. Box 1450
Alexandria, Virginia 22313-1450
www.uspto.gov

APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.
09/164,580	10/01/1998	RICHARD W. ARNOLD	TI-22561	6836
23494	7590	02/21/2008	EXAMINER	
TEXAS INSTRUMENTS INCORPORATED P O BOX 655474, M/S 3999 DALLAS, TX 75265			GEYER, SCOTT B	
ART UNIT	PAPER NUMBER			
	2812			
NOTIFICATION DATE	DELIVERY MODE			
02/21/2008	ELECTRONIC			

Please find below and/or attached an Office communication concerning this application or proceeding.

The time period for reply, if any, is set in the attached communication.

Notice of the Office communication was sent electronically on above-indicated "Notification Date" to the following e-mail address(es):

uspto@ti.com

uspto@dlemail.itg.ti.com

DETAILED ACTION

Interference

The use of an affidavit filed under 37 CFR 1.131 on November 6, 2001 in this application is not acceptable to establish prior invention where the rejection is based upon a U.S. patent to another that claims the same patentable invention. This fact was also detailed in the decision by the Board of Patent Appeals and Interferences, dated September 28, 2006 (starting on page 11 of the board's decision).

Therefore, the applicant is invited to follow the guidelines set forth in 37 CFR 41.202(a)(1)-(6) and (d) for interferences. Noted below are form paragraphs related to sections of 37 CFR 41.202:

(1) Applicant has failed to provide sufficient information to identify the application or patent with which the applicant seeks an interference. See 37 CFR 41.202(a)(1) and MPEP § 2304.02(a).

(2) Applicant has failed to (1) identify all claims the applicant believes interfere, and/or (2) propose one or more counts, and/or (3) show how the claims correspond to one or more counts. See 37 CFR 41.202(a)(2) and MPEP § 2304.02(b).

(3) Applicant has failed to provide a claim chart comparing at least one claim of each party corresponding to the count. See 37 CFR 41.202(a)(3) and MPEP § 2304.02(c).

(4) Applicant has failed to provide a detailed explanation as to why applicant will prevail on priority. See 37 CFR 41.202(a)(4), (a)(6), (d) and MPEP § 2304.02(c).

Applicant is given ONE MONTH or THIRTY DAYS, whichever is longer, from the mailing date of this communication to correct the deficiency(ies). THE PROVISIONS OF 37 CFR 1.136 DO NOT APPLY TO THE TIME SPECIFIED IN THIS ACTION.

Conclusion

Any inquiry concerning this communication or earlier communications from the examiner should be directed to Scott B. Geyer whose telephone number is (571) 272-1958. The examiner can normally be reached on weekdays, between 9:00am - 5:00pm. If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Michael Lebentritt can be reached on (571) 272-1873. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300. Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see <http://pair-direct.uspto.gov>. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free). If you would like assistance from a

Art Unit: 2812

USPTO Customer Service Representative or access to the automated information system, call 800-786-9199 (IN USA OR CANADA) or 571-272-1000.

/Scott B. Geyer/

Primary Examiner, Art Unit 2812